

(b) Individual setting mode

The individual setting mode can be set on the "Curl Adjustment screen" of the operation panel.

The following list shows the relationship between "Strength of correction" and "Curl Adjustment screen."

Strength of correction "Strong": Setting value "+2 or -2"

Strength of correction "Weak": Setting value "+1 or -1"

HM	Paper Size	Paper weight (g/m ²)	Curl		Humidification	De-curler			
			Direction	Strength of correction		/1	/2	/3	/4
Not provided	All Size	50 to 135	Convex	Strong	x	○	x	Parallel	0 degree (parallel)
				Weak	x	○	x	Pressure	30 degrees
			Concave	Strong	x	x	○	Parallel	0 degree (parallel)
				Weak	x	x	○	Pressure	30 degree
		136 to 162	Convex	Strong	x	○	○	Pressure	45 degrees
				Weak	x	○	○	Pressure	37.5 degrees
			Concave	Strong	x	○	○	Pressure	15 degrees
				Weak	x	○	○	Pressure	22.5 degrees
	Other than postcard/A6	163 to 300	Convex	Strong	x	x	x	Pressure	45 degrees
				Weak	x	x	x	Pressure	37.5 degrees
			Concave	Strong	x	x	x	Pressure	15 degrees
				Weak	x	x	x	Pressure	22.5 degrees
	Postcard/A6	163 to 300	Convex	Strong	x	○	x	Pressure	45 degrees
				Weak	x	x	x	Pressure	45 degrees
			Concave	Strong	x	x	○	Pressure	15 degrees
				Weak	x	x	x	Pressure	15 degrees
	All Size	301 to 350	-	-	x	x	x	Pressure	30 degrees
Provided	All Size	50 to 135	Convex	Strong	○ / x ^{*1}	○	x	Parallel	0 degree (parallel)
				Weak	○ / x ^{*1}	○	x	Pressure	30 degrees
			Concave	Strong	○ / x ^{*1}	x	○	Parallel	0 degree (parallel)
				Weak	○ / x ^{*1}	x	○	Pressure	30 degree
		136 to 162	Convex	Strong	○ / x	○	○	Pressure	45 degrees
				Weak	○ / x	○	○	Pressure	37.5 degrees
			Concave	Strong	○ / x	○	○	Pressure	15 degrees
				Weak	○ / x	○	○	Pressure	22.5 degrees
	Other than postcard/A6	163 to 300	Convex	Strong	○ / x	x	x	Pressure	45 degrees
				Weak	○ / x	x	x	Pressure	37.5 degrees
			Concave	Strong	○ / x	x	x	Pressure	15 degrees
				Weak	○ / x	x	x	Pressure	22.5 degrees
	Postcard/A6	163 to 300	Convex	Strong	○ / x	○	x	Pressure	45 degrees
				Weak	○ / x	x	x	Pressure	45 degrees
			Concave	Strong	○ / x	x	○	Pressure	15 degrees
				Weak	○ / x	x	x	Pressure	15 degrees
	All Size	301 to 350	-	-	○ / x	x	x	Pressure	30 degrees

The following shows the meaning of ○ and x.

○: Use the function

x: Not use the function

*1 No humidification on coated/color paper.